



9/05/070  
United States Department of the Interior

BUREAU OF LAND MANAGEMENT

Moab District

San Rafael Resource Area

900 North 700 East

Price, Utah 84501



IN REPLY REFER TO:

3809

(UTU-70949)

(UTU-71050)

(UT-067)

N. George Jackson  
John D. Jackson  
HC 70 Box 70  
Caineville, Utah 84775-9606

OCT 1 2 1993

Dear Messrs. Jackson:

We have conducted a field inspection on the trails which you propose blading and we have found some inaccuracies in the submitted maps. The road on the west side of Tomsich Butte was found to be accessed at the southwestern part of Tomsich Butte, rather than the northwestern part. We have marked a copy of your map in green to show our findings. Also, the southern trail has more of diagonal slant to it rather than going straight in. Please make the necessary corrections to your map.

We would like to clarify what is meant by maintaining the roads, portals, and dumps. Does road maintenance refer to blading the entire road or just part of it? Also, maintaining the portals and dumps is rather nebulous. Did you have anything specific in mind?

If you have any questions, please contact Neil Simmons or my staff at 801-637-4584.

Sincerely,

PENELOPE J. SMALLEY

Area Manager

Enclosure  
Map

cc: Bryant Anderson  
Emery County Planning and Zoning  
P.O. Box 297  
Castle Dale, Utah 84513  
Kiran Bhayani  
Utah Department of Environmental Health  
Division of Water Quality  
P.O. Box 16690  
Salt Lake City, Utah 84116-0690  
Holland Shepherd  
Division of Oil, Gas and Mining  
355 West North Temple Street  
3 Triad Center  
Salt Lake City, Utah 84180-1203

RECEIVED

OCT 1 4 1993

DIVISION OF  
OIL, GAS & MINING